



Aviation Investigation Factual Report

Location:	Fort Myers, Florida	Incident Number:	ERA09IA240
Date & Time:	April 12, 2009, 14:05 Local	Registration:	N559DW
Aircraft:	Beech B200	Aircraft Damage:	None
Defining Event:	Miscellaneous/other	Injuries:	1 Fatal, 4 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Factual Information

On April 12, 2009, about 1405 eastern daylight time, a Beech B200, N559DW, registered to White Equipment Leasing LLC, was landed uneventfully by a pilot-rated passenger at Southwest Florida International Airport (RSW), Fort Myers, Florida, following cardiac incapacitation of the pilot shortly after takeoff from Marco Island Airport (MKY), Marco Island, Florida. Visual meteorological conditions (VMC) prevailed at the time and an instrument flight rules (IFR) flight plan was filed for the 14 Code of Federal Regulations (CFR) Part 91 personal flight from MKY to Jackson-Evers International Airport (JAN), Jackson, Mississippi. The airplane was not damaged and the certificated airline transport pilot was pronounced dead after arrival. The pilot-rated passenger and three additional passengers were not injured. The flight originated from MKY about 1315.

The airplane owner who is a certificated private pilot with airplane single engine land rating was in the co-pilot's seat for the incident flight. He stated that the incident pilot flew the incident airplane to MKY that day, and arrived there about 1245 to 1300. The pilot assisted with loading baggage and the owner stated he did not notice anything wrong with him. Additionally, the pilot did not mention about having any physical problems.

The owner also stated that approximately 5 to 8 minutes after takeoff while flying northbound and climbing, the pilot said, "OK, climb checklist," and using the checklist, verbalized each item and pointed to the respective instrument/switch. After completion, the pilot put the checklist away, and the flight continued on the northerly heading.

Safety Board review of a voice tape from Miami Air Route Traffic Control Center (Miami ARTCC) revealed the pilot established contact with the facility, and the controller cleared the flight to climb to 14,000 feet mean sea level (msl). The pilot did not respond to the clearance from the controller. Approximately 20 seconds later, the owner who was seated in the co-pilot's seat declared an emergency advising the controller of the pilot incapacitation and the need to speak with someone familiar with the B200 airplane.

The owner later stated that approximately 1 to 3 minutes after completion of the climb checklist, while flying between 5,000 and 6,000 feet msl, he noticed the pilot's head was down and both hands were at his sides. The owner attempted to get the pilot's attention but he made an audible sound which increased in intensity, and the pilot's right hand fell off his thigh. The pilot did not make any further sounds.

Further review of the voice tape from Miami ARTCC revealed the flight continued on a northerly heading climbing to approximately 17,300 feet msl. Another Miami ARTCC controller talked the owner through the process of disengaging the autopilot, descending, and heading changes. Air traffic control communications were then transferred to Fort Myers Approach Control. Review

of voice and radar data from Fort Myers Approach Control revealed the controller provided information to the owner regarding information concerning the landing gear, flaps, power levers, and airspeed settings. The flight was vectored for a 15 mile long final approach for runway 6 at RSW, and the airplane was landed uneventfully. The owner taxied onto a taxiway where the engines were secured and medical personnel were standing by.

Forensic toxicology was performed on specimens of the pilot by the FAA Bioaeronautical Sciences Research Laboratory (CAMI), Oklahoma City, Oklahoma, and also by Wuesthoff Reference Laboratory (Wuesthoff Laboratory), Melbourne, Florida. The toxicology report by CAMI indicated the results were negative for carbon monoxide, cyanide, and volatiles. The report detected an unspecified amount of Atropine in the blood specimen. The toxicology reports by Wuesthoff Laboratory was negative in the femoral blood specimen for the immunoassay screen and volatiles. Caffeine was detected in the femoral blood specimen. The results were negative in the immunoassay drug screen for the submitted urine specimen.

The NTSB Medical Officer reviewed the medical records maintained by the FAA Aerospace Medical Certification Division on the pilot. The following information was extracted from those records:

The pilot's most recent application for 3rd class Airman Medical Certificate, dated 11/20/2008, indicates "Yes" in response to "Do You Currently Use Any Medication," and notes clopidogrel, aspirin, amlodipine, and simvastatin. The application notes "Yes" to "Heart or vascular trouble" and to "High or low blood pressure." Under "Explanations" is noted, in part, "Stent in right coronary artery." Height is noted as 70 inches and weight as 217 pounds. Blood pressure is noted as 136/70.

A letter from the pilot's Aviation Medical Examiner dated 1/6/2009 notes, in part, that the pilot "... underwent his physical for class II FAA certificate on 11/20/2008. He had undergone a stent to the right coronary artery ... Initially he was found with a slight abnormality in his EKG and treadmill confirmed there was a lesion. This was confirmed by coronary angiogram, angioplasty, and stent. Postoperatively, he has done well. His medications are Zocor [simvastatin] 40 mg, Norvasc [amlodipine] 5 mg, Plavix [clopidogrel] 75 mg and aspirin 325 mg, all taken once a day. His blood pressures have been normal. He has no problems with any of the medications as far as any side effects. He has a negative treadmill and an essentially normal cath except for the stent that is in place and open. He never had any chest pain, shortness of breath, or fatigue from the coronary artery disease. He has no symptoms in regards to that at the present time. He is in excellent health ... "

Report of exercise stress test performed 9/24/2008 notes, in part, "The patient exercised on a treadmill for a total of 6.05 minutes, on a standard Bruce Protocol, reaching >100% of the maximum age predicted heart rate. The maximum blood pressure reached was 176/88. The patient reached a peak heart rate of 166 bpm. ... The exercise portion of the test was non-diagnostic. The patient displayed good exertional capacity during stress. ... During rest and stress imaging, there was a small fixed photopenic defect in the lateral wall, suggestive of

scar. On the gated portion of the study, wall motion is normal and showed no wall motion abnormality. Patient has an ejection fraction of 46%. T.I.D. [transient ischemic dilation] Index is 0.89. ... This study suggests scar in the distribution of the Circumflex. ..."

A report of cardiac catheterization performed 11/10/2008 notes, in part:

... Left main – Normal

Left anterior descending artery – Normal caliber vessel with diffuse luminal irregularities and tortuosity throughout its course. This vessel presents with a proximal 30% stenotic narrowing. Left circumflex artery – Normal caliber vessel with diffuse luminal irregularities and tortuosity throughout its course. Very small distally, and has a mid total occlusion, filled distally by collaterals from the left anterior descending, unchanged from cardiac catheterization performed previously.

Right coronary artery – Large caliber vessel, dominant vessel, patent at the previous sites of stenting. Has a mid aneurysmal dilatation and diffuse luminal irregularities, but no significant high-grade stenosis. Dominant vessel.

Ejection fraction of 50% with preserved left ventricular systolic function. ...

An FAA cardiology consultant report dated 2/19/2009 notes, in part, that the pilot "...had a coronary episode in March of 2008 at which time he underwent cardiac catheterization and stent deployment in his right coronary artery. The right coronary artery has multiple plaques and total proximal stents, which are patent and the vessel distal to the stenting is patent. There is a fairly large coronary artery aneurysm in the mid-course of the right coronary artery. The vessel is patent both proximal and distal to the aneurysm. No evidence of ischemia either electrocardiographically or scintigraphically on the stress test. The basic electrocardiogram is suggestive of an old inferior myocardial infarction and this is confirmed scintigraphically by the fact that the basal portion of the left ventricle is not very contractile. On the basis of these findings, I think the airman is qualified for Special Issuance Limited 2nd Class certification and he should have the usual follow-up."

An Authorization for Special Issuance of a Medical Certificate dated 2/23/2009 notes, in part, "... The medical evidence reveals a history of coronary heart disease that has required treatment (percutaneous transluminal coronary angioplasty with intracoronary stent placement), hypertension, and use of medication. You are ineligible for airman medical certification ... However, based on the complete review of the available medical evidence, I have determined that you may be granted Authorization for special issuance second-class medical certification ... This Authorization expires on November 30, 2009. Consideration for a new Authorization will be contingent upon receipt of the following ... Approximately 60 days prior to the expiration of this Authorization ... and at subsequent 12-month intervals, a report of a current cardiovascular evaluation and current laboratory data ... a report of a current maximal treadmill stress test. ... On or about October 1, 2010, and at subsequent 24-month intervals, a report of a current SPECT radionuclide myocardial perfusion study performed in conjunction with a maximal treadmill stress test. ..."

The NTSB Medical Officer reviewed the report of autopsy performed on the pilot at the Office

of the District 21 Medical Examiner in Fort Myers, Florida. The following information was extracted from that report:

“Cause of Death” is noted as “Hypertensive and Arteriosclerotic Cardiovascular Disease.”

Under “Evidence of Medical Therapy” is noted, “An endotracheal tube is identified within the oral cavity and is properly situated. Defibrillator pads are identified on the left upper chest and left upper back. Underlying the left anterior chest defibrillator pad are multiple, dried, red-orange marks consistent with defibrillation. The left pretibial area has an intraosseous catheter.”

Under “Internal Examination” is noted, in part:... The pericardial sac is intact and contains a normal amount of clear, yellow pericardial fluid. The enlarged, 460 gram heart has a smooth, glistening epicardial surface associated with an increased amount of subepicardial fat. The coronary arteries arise normally and distribute in a right dominant pattern. Identified within the right main coronary artery and proximal aspect of the right coronary artery is an appreciable stent which is submitted ... for analysis. The left anterior descending coronary artery has two, separate, appreciable atherosclerotic lesions, one in the proximal distribution and one in the mid-distribution of that vessel. The maximum estimated obstruction of atherosclerosis in the left anterior descending coronary artery is 50%. The left circumflex coronary artery is nearly occluded by atherosclerotic disease. The remaining coronary vessels have minimal appreciable atherosclerotic disease. The atria are mildly dilated bilaterally. Both ventricles are dilated. The left ventricular free wall is hypertrophic and measures up to 1.9 centimeters in greatest thickness. The papillary muscles are hypertrophic. The myocardium is red-brown, except for a focal area of gray-yellow fibrosis located in the inferior wall of the left ventricle, near the interventricular septum. This area of fibrosis is grossly consistent with a remote myocardial infarction and measures up to 2.2 centimeters in greatest dimension. The remaining myocardium is red-brown and has no evidence of acute myocardial ischemia. The mitral valve leaflets are focally hooded and redundant. The remaining pulmonic, tricuspid, and aortic valves are grossly unremarkable. The root of the aorta is slightly dilated and has minimal appreciable atherosclerotic disease. The coronary ostia are patent.

A cardiovascular pathology report performed regarding a section of “right coronary artery with stent” notes, in part:

History: ... subject was piloting a multi-engine turbo prop plane when he became unresponsive, plane was safely landed by student pilot; initial cardiac rhythm was v-fib that progressed to PEA [pulseless electrical activity] and asystole.

Received in formalin is a segment of right coronary artery measuring 14 x 8 x 5 mm. Faxitron x-ray shows focal calcification and a Cypher stent that has been transected at one end, measuring 13 x 3.5 mm. Histologic sections show stent struts that are well apposed to the vessel wall and are completely covered. Mild chronic inflammation with giant cells surrounds some struts, but there is no persistent fibrin deposition. One section shows thin-capped

fibroatheromatous plaque formation with necrotic core overlying stent struts. Near the transected end of the stent there is mild in-stent restenosis with approximately 25% luminal narrowing by neointimal proliferation. There is no luminal thrombus.

Pilot Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	67, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine	Toxicology Performed:	Yes
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	November 20, 2008
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	March 17, 2009
Flight Time:	11560 hours (Total, all aircraft), 10420 hours (Pilot In Command, all aircraft), 40 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Other flight crew Information

Certificate:	Private	Age:	56, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	October 16, 2008
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N559DW
Model/Series:	B200	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	BB-1036
Landing Gear Type:	Retractable - Tricycle	Seats:	10
Date/Type of Last Inspection:	July 30, 2008 Continuous airworthiness	Certified Max Gross Wt.:	12500 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:	6792 Hrs	Engine Manufacturer:	U/A CANADA
ELT:	Installed, not activated	Engine Model/Series:	PT6A SERIES
Registered Owner:	WHITE EQUIPMENT LEASING LLC	Rated Power:	715 Horsepower
Operator:	WHITE EQUIPMENT LEASING LLC	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RSW,30 ft msl	Distance from Accident Site:	
Observation Time:	13:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	30°C / 17°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Marco Island, FL (MKY)	Type of Flight Plan Filed:	IFR
Destination:	Jackson, MS (JAN)	Type of Clearance:	IFR
Departure Time:	13:15 Local	Type of Airspace:	

Airport Information

Airport:	Southwest Florida Int'l RSW	Runway Surface Type:	Asphalt
Airport Elevation:	30 ft msl	Runway Surface Condition:	Dry
Runway Used:	06	IFR Approach:	None
Runway Length/Width:	12000 ft / 150 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	None
Passenger Injuries:	4 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal, 4 None	Latitude, Longitude:	26.536111,-81.755279(est)

Administrative Information

Investigator In Charge (IIC): Monville, Timothy

Additional Participating Persons: Robert H Potts; FAA/FSDO; Orlando, FL

Report Date: February 23, 2010

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=73642>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).